



Autore:	<i>Daniele Cecconi, Michele Bassi</i>
Data:	<i>08/10/2025</i>
Revisione documento:	<i>Rev03</i>

Modbar Pour Over Alerts and Alarms

Modbar Pour Over Alarms and Warnings List

Alerts/Alarms	Full Code	Code on Display	Condition/Parameter
MPO_MODULE_NO_ALARM	0x0001000		
MPO_MODULE_ALARM_BOLIER_PROBE_SC	0x0001001	1001	Boiler probe short circuit alarm.
MPO_MODULE_ALARM_BOLIER_PROBE_OC	0x0001002	1002	Boiler probe open circuit alarm.
MPO_MODULE_ALARM_BOLIER_PROBE_OVERTEMP	0x0001003	1003	Boiler probe overtemperature alarm.
MPO_MODULE_ALARM_BOLIER_PROBE_NOT_HEATING	0x0001004	1004	Boiler not heating alarm.
MPO_MODULE_ALARM_HEATER_BROKEN	0x0001005	1005	Boiler heater broken.
MPO_MODULE_ALARM_WRONG_CONNECTION	0x0001006	1006	Wrong Connection
MPO_MODULE_ALARM_HWID_NOT_RECOGNIZED	0x0001007	1007	Board HW ID not recognized
MPO_TAP_NO_ALARM	0x0002000		
MPO_TAP_ALARM_PROBE_SC	0x0002001	2001	TAP probe short circuit alarm.
MPO_TAP_ALARM_PROBE_OC	0x0002002	2002	TAP probe open circuit alarm.
MPO_TAP_ALARM_PROBE_OVERTEMP	0x0002003	2003	TAP probe overtemperature alarm.
MPO_TAP_ALARM_PROBE_NOT_HEATING	0x0002004	2004	TAP not heating alarm.
MPO_TAP_ALARM_HEATER_BROKEN	0x0002005	2005	TAP heater broken.
MPO_TAP_ALARM_WRONG_CONNECTION	0x0002006		

Note:

SC = Short Circuit

OC = Open Circuit

Guidelines for troubleshooting in the event of an alarm

Code on Display	Condition/Parameter	Description	Possible cause (from more probable to least probable)
1001	Boiler probe short circuit alarm.	The main board is trying to read the temperature of the module boiler probe. But the probe is seen as a short circuit.	<ul style="list-style-type: none"> The temperature probe is broken in short circuit. The temperature probe cable insulation is broken, and the cable is in short circuit. The connector on the Main board is in short circuit.
1002	Boiler probe open circuit alarm.	The main board is trying to read the temperature of the module boiler probe. But the probe is seen as an open circuit.	<ul style="list-style-type: none"> The temperature probe is not connected to the main board. The temperature probe is broken in open circuit. The temperature probe cable is broken, and the cable is in open circuit. The connector on the Main board is broken.
1003	Boiler probe overtemperature alarm.	The main board is reading the temperature of the module boiler probe. The temperature is higher than the allowed maximum temperature.	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet. Heater control cable from SSR to Main Board.



			<ul style="list-style-type: none"> Some unexpected operative conditions have caused the module to overheat. Try to identify the outline.
1004	Boiler not heating alarm.	The main board is trying to heat up the module boiler, but the temperature is not rising.	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet. Heater control cable from SSR to Main Board. The Heater safety thermal protections are broken. The Heater is broken The SSR is broken
1005	Boiler heater broken.	The main board is not heating the module boiler, but the temperature keeps rising. TURN OFF THE MACHINE IMMEDIATELY	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet. Heater control cable from SSR to Main Board. The Heater is broken Some unexpected operative conditions have caused the module to overheat. Try to identify the outline.
1006	Wrong Connection	The main board has checked the connections between the module and the TAP, and has found the temperature behavior to be crossed (not linear) between TAP1 and TAP2.	<ul style="list-style-type: none"> Check that TAP1 is configured as TAP1, and connected to the two module connectors dedicated to TAP1. Check that TAP2 is configured as TAP2, and connected to the two module connectors dedicated to TAP2
1007	Board HW ID not recognized	The HW ID configuration in not recognized.	<ul style="list-style-type: none"> Check the Jumper on JP4 on the main board, for Modbar P.O. the jumper should be on position "A".
2001	TAP probe short circuit alarm.	The main board is trying to read the temperature of the TAP boiler probe. But the probe is seen as a short circuit.	<ul style="list-style-type: none"> The temperature probe is broken in short circuit. The temperature probe cable insulation is broken, and the cable is in short circuit. The interconnections between the TAP and the Module Main Board have some pin in short circuit. The connector on the Main board has some pin in short circuit.
2002	TAP probe open circuit alarm.	The main board is trying to read the temperature of the TAP boiler probe. But the probe is seen as an open circuit.	<ul style="list-style-type: none"> The temperature probe is not connected to the main board through the various interconnections. The temperature probe is broken in open circuit. The temperature probe cable is broken, and the cable is in open circuit. The connector on the Main board is broken.
2003	TAP probe overtemperature alarm.	The main board is reading the temperature of the TAP boiler probe. The temperature is higher than the allowed maximum temperature.	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet, through Main Board. Check that TAP1 is configured as TAP1, and connected to the two module connectors dedicated to TAP1. Check that TAP2 is configured as TAP2, and connected to the

La Marzocco S.r.l. Headquarters: Via La Torre 14/H, Loc. La Torre, 50038 - Scarperia (FI), Italy | Phone +39 055 849191 | Fax +39 055 8491990 | info@lamarzocco.com | www.lamarzocco.com
La Marzocco S.r.l. Legal Address: Viale Giacomo Matteotti 25, 50121 - Florence (FI), Italy | Tax code, VAT code and Florence Business Register: no. 04040140487, Stock Capital: Euro 52.000,00 fully paid up.

The text and any attachments transmitted contain confidential information owned by La Marzocco S.r.l. and are intended only for the person or entity to whom they are addressed. The information and/or data contained in this document are confidential and their confidentiality is protected by the pro tempore applicable laws and/or regulations on the matter. Reading by third parties, copying, any action deriving from the knowledge of the information and/or data, as well as any use that is not previously authorized in writing by La Marzocco S.r.l., are strictly prohibited.



			<p>two module connectors dedicated to TAP2</p> <ul style="list-style-type: none"> Some unexpected operative conditions have caused the TAP to overheat. Try to identify the outline.
2004	TAP not heating alarm.	The main board is trying to heat up the TAP boiler, but the temperature is not rising.	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet, through Main Board. The Heater safety thermal protections are broken. The Heater is broken The Main Board SSR is broken
2005	TAP heater broken.	The main board is not heating the TAP boiler but the temperature keeps rising. TURN OFF THE MACHINE IMMEDIATELY	<ul style="list-style-type: none"> If the heater was working previously, and maintenance has been performed. Check the machine wiring. Heater cables from heater to power inlet, through Main Board. Check that TAP1 is configured as TAP1, and connected to the two module connectors dedicated to TAP1. Check that TAP2 is configured as TAP2, and connected to the two module connectors dedicated to TAP2 The Heater is broken Some unexpected operative conditions have caused the TAP to overheat. Try to identify the outline.